



AMERICA'S #1 POOL SURFACE COATING

EXTRA STRONG 40ML - COATING -

(2 COATS)

FULLY CURED 24-48 HOURS (AT A TEMPERATURE OF 70°F)

100% MAXIMUM BOND STRENGTH

SELF LEVELING

ULTRA LOW VOCs

AND NO FOUL ODORS

MILDEW INHIBITING

BEST CHLORINE & CHEMICAL **BARRIER**

1 UNIT (3 GALLONS) OF PARTS A/B MIXED covers a max of 300 sq/ft

TRUSTED BY AMERICA'S LARGEST CORPORATIONS

UV **STABLE** **LOW ENVIRONMENTAL IMPACT**



POOLPOXI IS TREATED WITH MICROBAN, A PERSISTENT ANTIMICROBIAL THAT COMBATS

BACTERIA, ALGAE, AND OTHER MICROBES.

PoolPoxi contains Microban, a built-in antifungal treatment that is an intrinsic part of PoolPoxi, both throughout the thickness of the film and at its surface. When microbes come into contact with the PoolPoxi surface, Microban protection penetrates the cell wall of the microbe and disrupts key cell functions so that the microbe cannot function, grow or reproduce. It's little ideas like this that make PoolPoxi a huge idea for your pool.

ALL OUR COATINGS ARE SUPER CHARGED BY SAFERESIN TECHNOLOGY.



MIX RATIO 2:1

CONTRIBUTES TOWARD VITAL LEED PROJECT POINTS

LEED BD+C / Low Emitting Materials: 3 Points LEED ID+C / Low Emitting Materials: 3 Points

(supporting documentation available upon request) Learn more about Leed Certification at: leed.usgbc.org

RECOMMENDED SUBSTRATES

Gunnite/Marcite, Concrete, Fiberglass, Marble, Acrylic





PoolPoxi TESTIMONIALS

IMPROVING THE WORLD ONE PROJECT AT A TIME!

BUTLER, GA





PROJECT: 40 year old residential pool in very bad repair and not holding water. Customer got several different quotes from pool contractors that were approximately \$25,000 for repairs.


SOLUTION: Customer chose to use the PoolPoxi Top Coat Epoxy Coating system. Spent \$5500 in coating material and hired an installer to complete project. Pool surface was completely restored and leaking stopped.

CUSTOMER RESPONSE:

The PoolPoxi Top Coat system saved us thousands of dollars and we can now enjoy our pool again. We highly recommend PoolPoxi Top Coat to anyone needing to refurbish their pool.

-Ward Edwards

DESOTO, MO





PROJECT: Gunnite pool with disintegrating surface.

SOLUTION: Customer chose to use the PoolPoxi Top Coat Epoxy Coating System to refurbish pool surface. Used PoolPoxi primer to tie the existing Gunnite surface together and then installed the PoolPoxi Top Coat top coat as the finish layer. Customer spent \$2,200 in material and did the installation themselves.

CUSTOMER RESPONSE:

The staff at PoolPoxi were extremely helpful and we could not have pulled this project off without them. The PoolPoxi Top Coat product is simply amazing and our pool looks like new!

-Bonnie Graves

KAILUA KONA, HI





PROJECT: Neglected residential pool with plaster walls that were disintegrating. Customer received quotes of \$20,000 plus to repair and resurface.

SOLUTION: Customer chose the PoolPoxi Top Coat Epoxy Coating System to resurface pool once the holes and cracks had been repaired. The total material cost was approximately \$2000 to resurface the entire pool.

CUSTOMER RESPONSE:

This is the strongest epoxy system I have ever worked with. I am excited about the finished product!

-Roland Ribordy